


# TEA BREWERS TROUBLESHOOTING GUIDE



MODELS: TCTS10000, TCTS10200, TCTT10000, TCTS10600

# PARTS IDENTIFICATION



PART #	DESCRIPTION
1. WC-2977-101K	KIT,SPRAYHEAD FITTING PLASTIC
2. WC-37189	UCM KIT, LABEL & OVERLAY 120V TCTS/T
3. WC-29025	SPRAYHEAD, PURPLE ADVANCE FLOW
4. WC-66079	SPOUT ASSY, DILUTION PLASTIC
5. WC-6193-0	HEAT SINK ASSEMBLY
6. WC-37255	KIT, DUAL VALVE WATER INLET
7. WC-102	SWITCH, TOGGLE NON-LIT 25A 120/240VAC
8. WC-43062	GASKET, TANK LID
9. WC-5502-01	KIT, PROBE, ASSY WATER LEVEL W/HEX
	FITTING, O-RING & NUT
10. WC-904-04	HEATING ELEMENT 1600W 120V W/JMNUT

PART #	DESCRIPTION
11. WC-1438-101	SENSOR, TEMPERATURE TANK
12. WC-523	THERMOSTAT, MNL RESET 120/240V 25A
13. WC-5310	TUBING, 5/16" ID X 1/8" W SILICONE
14. WC-826L	VALVE, INLET 1GPM 120V 10W
15. WC-895-105	VALVE, INLET DUAL 120V 10W 2 GPM X .5 GPM
16. WC-801	VALVE, INLET BRASS .50 GPM 120V 10W
17. WC-37317	KIT, STRAIGHT FITTING & BUSHNG
18. WC-37365	KIT, FITTING TANK INLET
19. WC-29044	SLEEVE, OVERFLOW ASSY
20. WC-889	VALVE, DUMP LEFT 120V 12W

# PARTS IMAGES










































# TROUBLESHOOTING INSTRUCTIONS

# **POWER ISSUES**

#### The unit will not turn on:

- 1 Verify that the Panel Breaker is turned on.
- Verify that the Power Cord is properly connected to the receptacle.
- 3 Verify that the Toggle Switch is turned on
- Verify 120v on both sides of the Toggle Switch. If yes, proceed to #5. If no, replace Toggle Switch.
- Verify 120v on both sides of the Reset Thermostat. If yes, proceed to #6. If no, replace Reset T-Stat.
- 6 Verify 120v across pins #8 and #16 at the Molex connector. If yes, replace the UCM. If no, check and / or replace Wiring Harness.

# **HEATING ISSUES**

## Not heating:

Is the water level in the tank in contact with the water level probe? If not, See TANK FILLING ISSUES.

Yes: Verify 120 volts at the Heating Element. If 120 volts is present, replace the Heating Element.

No: Verify 120 volts to the Triac Gate: If yes, replace Triac. If no, replace UPM.

If the LCD does not read "Heating" verify correct Temperature programming, then replace the Temperature Sensor.

i If the water in the tank is not in contact with the probe – refer to tank filling issues. The unit will not heat until the water in the tank has contacted the probe.

## Overheating:

# Does the LCD read "Heating"?

Yes: Verify that resistance on temp Sensor reads less than 10k ohm. Verify correct mounting to tank. Replace sensor.

No: Check Triac for continuity between A1 & A2. If continuity is present, replace Triac. If there is no continuity, replace the UCM.

# **DILUTION ISSUES**

#### **Dilution Water is not flowing:**

- Verify 120v across the Dilution Valve Coil. If yes, replace Dilution Valve. If no, proceed to #2.
- 2 Replace the UCM.

# **Dilution Water flows continuously:**

Does Dilution Water continue to flow after the Toggle Switch is turned off? If yes, replace Dilution Valve. If no, replace the UCM.



# TROUBLESHOOTING INSTRUCTIONS - continued

## TANK FILLING ISSUES

#### Not filling:

- 1 Verify that the water supply is turned on.
- Verify 120v across the inlet valve. If yes, replace Inlet Valve. If no, proceed to #3.
- Remove Orange wire from the Probe. Does Tank start filling?

If yes, replace the Probe. If no, replace the UCM.

#### Overfilling:

Does the tank continue to fill after the Toggle switch is turned off?

If yes, replace the Inlet Valve. If no, proceed to #2.

Connect the Probe wire to chassis ground.
Does the Tank continue to fill?

If yes, replace the UCM. If no, replace the Probe.

# **BREWING ISSUES**

#### No water flows from the sprayhead:

- Ensure correct alignment of the sprayhead fitting and that the tubing is routed properly to allow for maximum water flow. (No Kinks). Adjust and secure as needed.
- Verify that the water level in the Tank is up to the Probe. If not, see \* Tank Filling Issues\*.
- Verify 120v across the Dump valve Coil. If yes, replace Dump Valve. If no, proceed to #4.
- Measure the resistance of the Dump Valve Coil. An "OPEN" or "0" (shorted) reading indicates a defective Dump Valve, and it should be replaced, ALONG with the UCM.

#### **Short Pots:**

- Ensure that the sprayhead is clean and free of debris. Clean or replace as needed.
- Reset the Brew & Dilution levels if necessary

#### **Overflowing the Pots:**

- Is the Sprayhead missing? Replace as needed.
- Ensure that the Tea container is empty before brewing.
- Reset the Brew & Dilution levels if necessary.
- Water flows from the Sprayhead continuously until the Toggle Switch is turned off.

Yes: Replace Dump Valve.

No: Check and replace Dump Valve and UCM.



# NOTES





# Wilbur Curtis Co., Inc.

6913 Acco Street, Montebello CA 90640 Customer Service: 800.421.6150 | 323.837.2300 csrassistance@wilburcurtis.com Tech Support: 800.995.0417 www.wilburcurtis.com