ASSEMBLY INSTRUCTIONS

Workmaster*



Please read and save these instructions. Read carefully and thoroughly. Always consult and follow the directions of a Qualified Person as defined by OSHA 1926.32(m) before attempting to assemble, install, operate or maintain the product described. Protect yourself and others by observing all safety information. Failure to comply with instructions could result in personal injury and/or death! Retain instructions for future reference. Assembly and installation of the Workmaster can be inherently dangerous. Always consult and follow the directions of a Qualified Person. Take all precautions necessary during assembly and installations.

Cotterman

TOOLS NEEDED

(2) 3/4" Wrench or (1) 3/4" Wrench & (1) 3/4" Socket/Ratchet



Safety Glasses



PARTS

FINISHED ASSEMBLY, ALL WMX:

- · Stile Assembly · Back Panel · Base Panel
- 1/2"-13x3 Hex Head Cap Screw, Zinc Plated, Grade 5, x6, A-301-1255
- 1/2"-13 Nylon Insert Hex Locknut, Zinc Plated, x6, A-301-4404

ADDITIONALLY FOR 11-15 STEP WMX:

- · Braces, x2
- 1/2"-13x1-1/4" Hex Head Cap Screw, Zinc Plated, Grade 5, x4, A-301-1500
- 1/2"-13 Nylon Insert Hex Locknut Zinc Plated, x4, A-301-4404





DANGER! Death or serious injury may occur if improperly assembled or used. Always consult and follow directions of a Qualified Person.

- Read and Understand these instructions fully before installing, assembling or using these ladders.
- Assembly and installation of these types of ladders can be inherently dangerous. Take all precautions necessary during assembly.
- · Always use a separate ladder or scaffold to finish assembly in high places.
- · Never climb a ladder that is not completely assembled.
- · Do not assemble, install or use a ladder with missing or damaged parts.
- · Use proper lifting mechanics when assembling a ladder.
- · Watch for, and avoid overhead electrical hazards and obstructions.


FAILURE TO HEED THESE WARNINGS MAY RESULT IN SERIOUS INJURY OR DEATH TO INSTALLATION PERSONNEL, LADDER USERS, OR BYSTANDERS.



Workmaster*

ASSEMBLY SETUP


- 1. Ladders up to 6-step may ship fully-assembled.
- 2. Lay the ladder on its side. Have as many people help as necessary to maneuver the ladder safely.
- Cut the banding to free the Back Panel, Base and Stile assembly. Remove the bolts and nuts from the Stile Mounting Brackets. Cut the zip-ties to free the Base Panel from the Back Panel. Remove the bolts and nuts from the Platform Mounting Holes: DO NOT DISCARD.




 Horizontal Side Braces, 11-15 step models only: Braces are bolted into lug and free end zip tied to stile. Remove zip tie and swing the Horizontal Side Braces to the Back Panel and secure using the bolts and nuts provided in place.



- Stand the ladder upright. Have as many people help as necessary to maneuver the ladder safely. Use proper lifting mechanics when assembling a ladder.
- 7. Tighten the bolts and nuts (on both sides) that connect the Stile, Back Panel, Base Panel and Horizontal Side Braces.



Workmaster



MAINTENANCE



DANGER! Death or serious injury may occur if improperly assembled or used. Always consult and follow directions of a Qualified Person.

- Make sure all hex-nuts and hex-head bolts are tightly fastened. All bolted connections MUST be secure.
- 2. Inspect upon receipt and before each use. Never climb if any components are damaged, bent or broken. All parts MUST be in good working order.
- 3. Check to make sure labels are visible and readable. Contact Cotterman® to replace any worn or missing label.
- 4. Front feet MUST be in firm contact with the floor when ladder is occupied.
- Keep clean, free from grease, oil and all slippery and foreign materials. Keep your shoes clean.