

Model-Specific Compatibility Notes [05/06/2015]:

TWT-48: standard. per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. building 9 production after 2/24/05 production date.

TBB-24-60G: Per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TDD-3CT-S: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

QA-60-24MB-L: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303 and 800397 controls.

TDD-2-S: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

TBB-3G: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously\n used before 2/1/05 prod. and serial no.1-3981744.models produced before 11/8/01 or serial no. 1-3192061 are 1/3hp coolers and 800366 totally retrofits. models produced after 11/8/01 to 6/??/02 are 1/2hp coolers and we will have to use 800303. used as standard production after 6/02 may require a relay. replaces the 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TD-95-38: per pcn 7784 started using again as 6/2/14, needs relay use kit 883694. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

TDD-4: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TUC-GAL-48-2: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. not used yet for o\'fallon production.

TSSU-60-24M-DS: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TD-48-18: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

TDD-2: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

TD-36-12-S: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

TBB-3G-S: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously\n used before 2/1/05 prod. and serial no.1-3981744.models produced before 11/8/01 or serial no. 1-3192061

are 1/3hp coolers and 800366 totally retrofits. models produced after 11/8/01 to 6/??/02 are 1/2hp coolers and we will have to use 800303. used as standard production after 6/02 may require a relay. replaces the 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TBB-24-48: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TDD-4-S: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TSSU-72-30MB: per pcn 7784 started using again as 6/2/14. . use kit 882636. replaces the 963056 used previously. replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TCM-84: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously.

TBB-3-S: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TSSU-48-12M-B: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TBB-24-GAL-48G-SD: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TBB-24-72G: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TBB-24-48G-SD: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TUC-48G: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. building 9 production after 2/24/05 production date.

TPP-119: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously.

TRCB-79: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303)9531n376; 800397)9531n393 ce; 800337)9531n374 ce controls.

TDD-2CT-S: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

QA-72-30MB: per pcn 7784 started using again as 6/2/14, requires relay. replaces the 963056 used previously. use kit 882636\n\n115v coolers use after 4/2002 production date & may require new relay 208v/220v this part totally retrofits.

TRCB-50: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303)9531n376; 800397)9531n393 ce; 800337)9531n374 ce controls.

TSSU-36-12M-B: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800397, 9531n393, 800313, and 9531n335 controls.

TDG-50-18: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TD-36-12: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

TDG-95-38: per pcn 7784 started using again as 6/2/14, needs relay use kit 883694. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

TBB-4: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TD-50-18: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

TDD-3: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

TM-95-28: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TSSU-36-08: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800397, 9531n393, 800313, and 9531n335 controls.

TDG-65-24: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TD-24-07: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously.

TUC-36: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously used after 4/1/05 production date.

TWT-48G: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. building 9 production after 2/24/05 production date.

TRCB-79-86: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303)9531n376; 800397)9531n393 ce; 800337)9531n374 ce controls.

TSSU-60-24M-B: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TSSU-60-24MB-DS: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TWT-36: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously used after 4/1/05 production date.

TM-65-18: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TBB-24-60: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

QA-48-18MB: per pcn 7784 started using again as 6/2/14. replaces the 800303 and 800397)9531n393 controls.

TSSU-48-12M: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TBB-24-72: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TBB-24GAL-60: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TBB-24GAL-72: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TSSU-48-18M: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TBB-24GAL-48: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TBB-2G: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TWT-48D-4: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. building 9 production after 2/24/05 production date.

TDD-3CT: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

TD-50-18-S: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303 and 800397 and 800313 controls.

TBB-2-S: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TUC-48: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. building 9 production after 2/24/05 production date.

TSSU-48-15M-B: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TDG-48-18: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TUC-GAL-48: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. not used yet for o\fallon production.

TBB-24GAL-48G: per pcn 7784 started using again as 6/2/14. replaces the 963056 used previously. replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TSSU-36-12M: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, and 9531n335 controls.

TSSU-72-30M: per pcn 7784 started using again as 6/2/14. . Use kit 882636. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TBB-4-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TUC-60-32: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TD-95-38-S: per pcn 7784 started using again as 6/2/14, needs relay use kit 883694. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TBB-4G-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously used between 8/29/03 production date to 2/1/05.

TDD-4CT: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TUC-48D-4: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. Building 9 production after 2/24/05 production date.

TSSU-60-21M: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TUC-60-32D-2: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TD-65-24-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TBB-3: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TM-48-13: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TSSU-72-30MB-DS: per pcn 7784 started using again as 6/2/14. . Use kit 882636. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TD-65-24: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TBB-24-48G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TBB-2: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TWT-60-32: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TSSU-48-18M-B: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TBB-4G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously\n used between 8/29/03 production date to 2/1/05.

TBB-2G-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TDD-2CT: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TSSU-60-24M: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TDD-3-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TDG-36-12: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TSSU-48-15M: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TWT-60-32D-2: Per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TDD-4CT-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TRCB-52: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TBB-24GAL-60G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TBB-24GAL-60G-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TSSU-48-12MB-LP: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TSSU-48-15MB-LP: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TSSU-48-18MB-LP: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TSSU-60-24MB-LP: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TSSU-60-24MB-DS-LP: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TUC-36-LP: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously used after 4/1/05 production date.

TUC-48-LP: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. Building 9 production after 2/24/05 production date.

TUC-48G-LP: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. Building 9 production after 2/24/05 production date.

TUC-48D-4-LP: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. Building 9 production after 2/24/05 production date.

TWT-48-LP: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. Building 9 production after 2/24/05 production date.

TWT-48D-4-LP: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. Building 9 production after 2/24/05 production date.

TPP-119D-8: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TDB-24-48: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TDD-3G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TDB-24-48-1-G-1: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TDB-24-48G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TSSU-72-30M-B-ST: per pcn 7784 started using again as 6/2/14. . Use kit 882636. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TSSU-60-24M-B-ST: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TDD-4G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously used between 8/29/03 production date and 2/1/05 .

TPDB48-24: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TPDB48-24G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TPP-119D-2: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TPP-119D-4: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TPP-119D-6: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TUC-48D-2: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. Building 9 production after 2/24/05 production date.

TUC-48D-2-LP: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. Building 9 production after 2/24/05 production date.

TWT-48D-2: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously pacific production used after 2/1/05 or approximate serial no. 1-4057603. Building 9 production after 2/24/05 production date.

TSSU-60-24M-B-DS-ST: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TSSU-72-30M-B-DS-ST: per pcn 7784 started using again as 6/2/14. . Use kit 882636. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TDG-95-38-S: per pcn 7784 started using again as 6/2/14, needs relay use kit 883694. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TRCB-82: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TUC-60-32HD: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TWT-60-32HD: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TSSU-48-18MB-D4: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TSSU-72-30MB-ST-D2: per pcn 7784 started using again as 6/2/14. . Use kit 882636. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TPBB48-24G-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TBB-GAL-3G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously\n\nmodels produced before 11/8/01 or serial no. 1-3192061 are 1/3hp coolers and 800366 totally retrofits. Models produced after 11/8/01 to 6/??/02 are 1/2hp coolers and we will have to use 800303. 115v coolers produced after 6/??/02 may require a relay. Replaces the 800397)9531n393 ce; 800337)9531n374 ce controls.

TSSU-72-18M-B: per pcn 7784 started using again as 6/2/14. . Use kit 882636. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TCGDZ-50: used after 7/29/14 for 220v only per pcn 7904. replaces the 960640 used before.

TBB-24-72-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TSSU-60-12M-B: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TDBD-48-2: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TDBD-48-4: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TSSU-72-24M-B-ST: per pcn 7784 started using again as 6/2/14. . Use kit 882636. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TRCB-82-84: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TRCB-52-60: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TDD-4CT-G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously used after 8/29/03 production date or approximate serial no. 1-3666717.

TSSU-60-15M-B: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TSSU-60-18M-B: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TSSU-72-12M-B: per pcn 7784 started using again as 6/2/14. . Use kit 882636. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TSSU-72-15M-B: per pcn 7784 started using again as 6/2/14. . Use kit 882636. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TRCB-82-86: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TPBB48-GAL-24G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TPDB-1G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TPDB-1: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TDB-24-48-GAL-1-G-1: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303 and 800397 and 800313 controls.

TRCB-72: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TSSU-36-15MB: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, and 9531n335 controls.

TPBB48-24G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TBB-24GAL-72G: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TUC-24: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TRCB-36: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TRCB-48: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TBB-24-48G-SD-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TSSU-72-30M-B-D-2: per pcn 7784 started using again as 6/2/14. . Use kit 882636. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TBB-24-72G-SD: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TBB-24-72G-SD-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TBB-24-48-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TUC-36-34: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TBB-24-48G-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TBB-24-60-S: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800313, 9531n335, 800397, 9531n393 ce, 800337, and 9531n374 ce controls.

TSSU-48-18MB-D2: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously. Replaces the 800303, 9531n376, 800397, 9531n393, 800313, 9531n335, 800337, and 9531n374 controls.

TFBB-24-48: per pcn 7784 started using again as 6/2/14. Replaces the 963056 used previously.

TUC-27WB-LP: N/A.

TUC-27DI-LP: N/A.