

Model-Specific Compatibility Notes [11/08/2016]:

TWT-48: N/A

TSSU-48-12: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TSSU-48-08: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TSSU-48-8M: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TUC-48G: N/A

TWT-48G: N/A

TUC-48F: N/A

TSSU-48-10: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TUC-48: N/A

TUC-GAL-48F: N/A

TWT-48F: N/A

TUC-48F-D: N/A

TSSU-48-8-LP: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TSSU-48-10-LP: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TSSU-48-12-LP: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TUC-48-LP: N/A

TUC-48G-LP: N/A

TWT-48-LP: N/A

TWT-48D-4-LP: N/A

TUC-48F-LP: N/A

TUC-48D-2: N/A

TUC-48D-2-LP: N/A

TWT-48D-2: N/A

TSSU-48-12D-2: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.

TSSU-48-10-HC: Will not work with a flat lid “night cover” there is not enough room between the flat lid and the edge of the countertop to place the service shelf bracket.