

Model-Specific Compatibility Notes [08/31/2015]:

TDBD-96-6: Used after 10/28/2004 production date. May require relay 800182 on 115v cabinets only order separately.

TSID-48-4: Started using 10/28/2004. Will require an 800182 relay if used to replace Ranco control previously used.

TSID-48-4-L: Started using 10/28/2004. Will require an 800182 relay if used to replace Ranco control previously used.

TDBD-96-3: Used after 10/28/2004. May require relay 800182 on 115v cabinets only- order separately.

TSID-96-6: Used after 10/28/2004 production date. May require relay 800182 on 115v cabinets only order separately.

TSID-48-2: Started using 10/28/2004. Will require an 800182 relay if used to replace Ranco control previously used.

TSID-48-2-L: Started using 10/28/2004. Will require an 800182 relay if used to replace Ranco control previously used.

TSID-96-3: Used after 10/28/2004 production date. May require relay 800182 on 115v cabinets only order separately.

TSID-36-4: Used before 9/17/2010 (pcn #4714).

TSID-36-2: Used before 9/17/2010 (pcn #4714).