

W-Series I-Bar Spare Parts Diagram





Figure 1. Spare Parts Diagram Overview


Last Update: 8/3/21

WHI SPARE PARTS DIAGRAM

Figure 2. Spare Parts Diagram Overview





Timer - #7



WHI SPARE PARTS DIAGRAM

Figure 3. Spare Parts Diagram Overview



WHI SPARE PARTS DIAGRAM

Item	Part #	Description	Comments
RKs	RK-Model#	REPLACEMENT KITS Includes (2) elements, (4) PTFE adhesives, and (1) blade if cutter unit (IC)	specify model # when ordering
1	Screw-M4x8	M4*8 Screw	
2	WHLH-7	Power Switch, 3P, 15A/125V (W-Series)	
3	WHA-33	Lamp (R), LED for E.G.O. E-00302 for (W-Series)	
4		Nut for Circuit Breaker	
5	WHA-30	Knob, Red for (W-Series)	
6	WHI-6	Nut for (Variable Resistor)	
7		Control Panel,Timer, PCB the Same,consists(2-11)	
7a	T-W-350I/350IC	Control Panel, Timer, 12", Circuit Breaker (7A)	for W-350I/IC
7b	T-W-500I/500IC	Control Panel, Timer, 20", Circuit Breaker (10A)	for W-500I/IC
7c	T-WH	Control Panel, Timer, (26", 30", 35"), CB (15A)	for W-650I/IC, W-750I/IC, 900I/IC
7d	PCB-WHI	PCB for the Control Panel - 10A	
8		Spring Washer	
9		Nut	
10	WHA-36	Variable Resistor - 1M (W-Series)	
11a	WHI-11a	Circuit Breaker, 7A	for W-350I/IC
11b	WHI-11b	Circuit Breaker, 10A	for W-500I/IC
11c	WHI-11c	Circuit Breaker, 15A	for W-650I/IC, W-750I/IC, 900I/IC
12	Screw-M4x8	M4*8 Screw	
13	WHI-13	Power Receptacle 3P	
14	WHI-14	Control Box	
15	WHA-43	Grommet (W-Series)	
16	PC-WH	Power Cord	
17		Screw 3* 15 for #18	
18	MSW-WHLH-WHI	Microswitch w/Long Arm for WHLH and WHI	
19	WHI-19	Limit Switch Holder	
20a	WHLH-67a	Spring Arm, 2.6 for WHI and WHLH	for W-350I/IC, W-500I/IC
20b	WHLH-67b	Spring Arm, 3.0 for WHI and WHLH	for W-650I/IC, W-750I/IC
20c	WHLH-67c	Spring Arm, 3.5 for WHI and WHLH	for W-900I/IC
21	WHI-21	Spring Holder, L-Bracket	
22		Upper Lever Arm	specify model # when ordering
23	WHLH-54	Lever Knob, Round (WHI and WHLH)	
24	WHI-24	Spring Washer M6 for# 23	
25	WHI-25	Screw M6*20 for #23	
26		Acrylic Plate - 3/4" Orange Plastic	specify model # when ordering
27	HE-specifymodel#	Heating Wire 0.8mm, 2.7mm	specify model # when ordering
28	TA-specifymodel#	PTFE Adhesive (Insulated Tape) 3/4" TA, 3mil	specify model # when ordering
29	WHI-29	Spring, for Hook Assembly	
30	WHI-30	Plastic Washer for Hook Assembly	
31	WHI-31	Spring Hook, for Hook Assembly	
31a	SHA-WHI	Spring Hook Assembly SHA-WHI includes (29-31)	

Figure 4. Spare Parts Diagram List (Table 1 of 2)

WHI SPARE PARTS DIAGRAM

Figure 5. Spare Parts Diagram List (Table 1 of 2)

Item	Part #	Description	Comments
32	TA-specifymodel#	PTFE Adhesive (Insulated Tape) 3/4" TA, 3mil	for I-Bars (w/o cutters)
	TZ-specifymodel#	PTFE Zone Adhesive 2", 5mil	for I-Bars (w/ cutters)
33	SR-specifymodel#	Silicone Rubber SR-	specify model # when ordering
34		Silicone Bracket	specify model # when ordering
35a	TRNS-W-350I/IC	Transformer (14")	for W-350I/IC
35b	TRNS-W-500	Transformer (20") #1035	for W-500I/IC
35c	TRNS-W-650/750	Transformer (26", 30") #1037	for W-650I/IC, W-750I/IC
35d	TRNS-W-900	Transformer (35", 40") #1039	for W-900I/IC
36		Screw M6*16	
37		Screw 3/8" 1 1/2	
38		Washer M6*16	
39	WHLH-40	Bushing - old gen	
40		Upper Lever Bracket (Left)	
41		Upper lever Bracket (Right)	
	WHLH-30a	Support Bracket Set	
42		Screw 3/8	
43	WHI-43	Bearing w/ Screw for Rollers	
44		Film Roller/each	
45		Shaft	
46		Screw M5*8	
47		Roller Fixed Plate	
48		Base Plate	
49		Bags Support/Film Separator	
50		Washer 5/16*23	
51		Screw 5/16	
52		Screw 5/16* 5/8	
53	WHLH-38	Rubber Foot (WHLH / WHI)	
54		Adhesive PTFE Tape 19mm	
56		PC Support	
		#57-68 for Sealers with Cutter	
57	WHLH-75	Bushing for Cutter Unit, Rubber Spacer for WHLH and WHI-C	
58	CB-WH	Cutting Blade Bracket	
58a	CBB-WH	Cutting Blade Bracket with Blade	
	CBB-WH-HD	Cutting Blade Bracket w/ Blade - Heavy Duty	
59	WHLH-76	Screw M5*30, Cutter Unit Bracket	
60	SRC-model#	Silicone for Cutter Unit for WHI and WHLH	specify model # when ordering
61	refer to WHLH #2	Square Tube for WHLH and WHI	
62	WHI-62	Screw - M4*25 for Square Tube for WHLH and WHI	
64	B-WH	Blade	
65	WHI-65	Spring for Square Tube for WHLH and WHI	
66	refer to WHLH #69	Silicone Bracket for Cutter Unit	
67	WHLH-73	Screw M3*8 for Blade	
68		Complete Cutter Unit	
69	WHI-69	Heat Gun Holder	
69a	WHI-69a	Fixed Plate for Heat Gun Holder	
70	WHI-70	Sponge Cushion for Handle	