


Tray Slide

Parts List




Tray Slide: 1 pcs



**M6x12mm Cross Groove Large
Flat Head Machine Thread Screws:**
SS-CFT-36-HC/SS-CFT-48-HC: 9pcs
SS-CFT-60-HC/SS-CFT-72-HC: 12pcs

1. Confirm the installation position. The tray slide can be installed at the front and rear of the SS-CFT units.



2. Pull out the installation hole cover from the desired position.
3. Install the tray slide and secure the screws according to the following diagram.

