



C10/DC10


WARNING CARD




1 Fill the solution tank and close the cap firmly



2 Plug the power cord to the right power supply (AC220V - AC110V)



3 Turn on the machine by sliding the switch. Half Speed-Full Speed



4 Adjust the droplet size by turning the nozzle on the front of the machine