

TECHNICAL SPECS



APPLICATION TEMPERATURE – above 50° F

SERVICE TEMPERATURE – 40° to 120° F

OUTDOOR – No, indoor only

MOISTURE RESISTANT – No

STORAGE TIPS – Store tape in a cool, dry location. Keep out of direct sunlight.

DIRECTIONS



Surfaces must be flat, dry and free of dirt and oil. Clean with isopropyl alcohol according to manufacturer's instructions. Use 4 inches of tape per 3 pounds of weight.

1. Apply tape to back of object vertically, allowing for even distribution of weight. Avoid touching surface of tape.
2. Tape can be torn by hand or cut and press to secure tape to object.
3. Remove liner and align object to desired placement.
4. Press firmly for 60 seconds as Gorilla Mounting Tape conforms to the surface and creates a strong, permanent bond.

Tips for Use:

- Holding weight is based on objects with a maximum depth of 0.75". Objects over 0.75" in depth put more stress on the bond and have an increased chance of failure.
- Tape must make contact with surface. If surface is uneven, tape will not be able to make contact and will not hold.
- Apply when temperature is above 50° F. In-use temperature range: 40°F to 120°F.