



Regency Glass Filler Station with 8" Glass Filler

#600GFWS4108



Technical Data

Length	12 11/16 Inches
Width	10 3/4 Inches
Height	1 3/4 Inches
Spout Length	3 7/8 Inches
Bowl Depth	1 3/4 Inches
Faucet Height	9 5/8 Inches
Bowl Front to Back	4 11/16 Inches
Bowl Left to Right	10 3/16 Inches
Drain Outlet Size	1 1/2 Inches
Features	NSF Listed

Features

- High-quality stainless steel construction
- Flow rate of 1.2 GPM
- Simple, hassle-free installation
- Includes glass filler with 8" of clearance
- Filler boasts an intuitive lever design

Certifications




Technical Data

Flow Rate	1.2 GPM
Gauge	18 Gauge
Included	Faucet
Installation Type	Deck Mounted
Material	Stainless Steel
Number of Faucets	1 Faucets
Spout Clearance	8 Inches
Style	Push Back
Type	Water Stations
Water Inlet Size	1/2 Inches

Notes & Details

Create a convenient water filler station in your business using this Regency glass filler station with 8" glass filler! Made with high-quality 18 gauge stainless steel for outstanding durability, the drip pan is made to withstand daily wear and tear in high-traffic establishments. Plus, it comes with a drop-in grid to provide a convenient platform for your glassware or tumblers. Additionally, the drip pan has a 1 1/2" IPS drain, and it is easy to install for a hassle-free user experience!

Providing 8" of clearance, the glass filler boasts plenty of room to accommodate all kinds of glassware, while its deck-mounted design and single hole base make it easy to install. With a dedicated glass filler, you can give your waitstaff more flexibility by placing it in the most convenient location for your workflow. An intuitive and familiar lever design makes it easy to use, too - just push the cup back against the lever and it will dispense from the nozzle. It's a great way to improve workflow and ensure all of your customers get a glass of clean, refreshing water. It installs using a 1/2" NPT male inlet.

 **WARNING:** This product can expose you to chemicals including lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. For more information, go to www.p65warnings.ca.gov.