

929839 Compatibility Notes - 06/07/2018	
Model	Notes
T-49F	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
T-49	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305/831357) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
T-19E	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
T-49F-2-G-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
TS-72FG	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
T-72-6	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT
TS-49G-4	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
T-49FZ	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
TS-53-4-G-4PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
TM-52G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-28G-2PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
T-72G-6	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
T-23-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOOR ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR.
T-23-1-G-1	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
T-23FG	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)

TS-72-6	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS THREE TOP DOORS.
TM-52-4	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS TWO TOP DOORS.
TS-23FG	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TM-74G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-49F-2-G-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
T-72FG	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-72F-6	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS THREE TOP DOORS.
T-23DT-1-G-1	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
T-72F	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS THREE DOORS
T-19FZ	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
T-23DT-G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
TS-49G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
T-35	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
TS-23-1-G-1	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR

TS-35	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
TS-23G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
T-17F-2	FOR TOP DOOR ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR.
T-72FZ	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS THREE DOORS
TS-35F	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
T-49FG	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-28G-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
TM-52	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
TH-23	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
TS-49F-4	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS TWO TOP DOORS.
T-35G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
T-23DT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOOR ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR.
T-49F-4	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS TWO TOP DOORS.

TS-53-4PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS TWO TOP DOORS.
TS-23	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
T-19F	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
TS-49-2-G-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
T-23G-PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-19FZ	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
T-19G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-49F	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
T-23G-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
TS-49-4	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS TWO TOP DOORS.
TS-72	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS THREE DOORS
T-23F-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOOR ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR.
T-49DT-G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-72F	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS THREE DOORS

TS-35G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-23F	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
T-23F	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
TM-74-6	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS THREE TOP DOORS.
T-49G-PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-19	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
T-72G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-72-3-G-3	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
T-19	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
TM-74	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS THREE DOORS
T-23RL	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
TS-23F-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOOR ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR.
T-23	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
T-49G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)

T-49DT-4	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS TWO TOP DOORS.
TS-28-2PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
TS-49FG	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TBB-24GAL-48G	OPTION. REQUIRES 1 PER DOOR
T-72F-6	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS THREE TOP DOORS.
TS-49DT-G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-23-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOOR ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR.
T-72	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS THREE DOORS
TS-28-2-G-2PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
T-49-2-G-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
TM-24	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
T-23G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-23G-PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TM-52F	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
TS-23G-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR

TM-74F	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS THREE DOORS
GDM-49	FOR COCA-COLA HOUSTON\'S SOLID DOORS. GOES INTO THE DOOR ITSELF. NOT RECOMMENDED FOR FIELD REPLACEMENT AS THE LOCK IS FOAMED IN PLACE. REQUIRES 1 PER DOOR. **REPLACES 831357. FILING MAY BE REQUIRED FOR LOCK FIT ON OLDER PRODUCTION. FILE THE FLATS OF THE DOUBLE D HOLE.**
TM-24F-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOOR ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR
T-23FZ	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
TM-24F	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
TS-49	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
TM-24-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOOR ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR
TS-72G-6	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
T-72-3-G-3	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
T-49DT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
T-35F	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
T-35FZ	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
T-49G-4	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
T-35FG	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TH-23G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)

T-49-4	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS TWO TOP DOORS.
T-49PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS FOUR DOORS
TS-72G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
T-49DT-1-G-1	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
TS-28	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115)
TS-28PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
TS-53	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
TS-53PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS FOUR DOORS
TS-28G-PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-53G-PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TS-28-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOOR ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR.
TS-53-4	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS TWO TOP DOORS.
TS-53G-4	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
TPDB48-24G	REQUIRES ONE PER DOOR
TM-24G	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)

T-23F-1-G-1	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
GDM-52TM-RL	**REPLACES 831357. FILING MAY BE REQUIRED FOR LOCK FIT ON OLDER PRODUCTION. FILE THE FLATS OF THE DOUBLE D HOLE.** REQUIRES 1 PER DOOR. CABINET HAS TWO DOOR.
TPBB48-24G-S	REQUIRES ONE PER DOOR
T-23PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
T-23FG-2	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115) BOTTOM DOORS HAVE LOCK BAR
TS-23PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) CABINET HAS TWO DOORS
T-49-4PT	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOORS ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR. REQUIRES 1 PER TOP DOOR. CABINET HAS TWO TOP DOORS.
TPBB48-24G	REQUIRES ONE PER DOOR
TS-53G-PT-2G-2S	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TUC-24G	N/A
T-19-1-G-1	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
TUC-36-34	OPTION
T-43	N/A
T-43F	N/A
TS-43	N/A
TS-43F	N/A
T-23G-PT-LD MCD1	N/A
T-43-HC	N/A
T-35-HC	N/A
T-49-HC	N/A
T-23G-2-HC~FGD01	N/A
T-23-HC	N/A
T-23F-HC	N/A

TS-23-HC	N/A
T-49G-HC-LD	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (872837) LOCK ASSEMBLY. (PCN #4115)
T-23G-HC	N/A
T-49F-HC	N/A
T-23DF-HC	N/A FOR TOP DOOR ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR.
T-43F-HC	N/A
T-23F-2-HC-MC	N/A
T-23G-PT-HC-LD	N/A
T-23G-DC~FGD01	N/A
T-72-HC	N/A
T-72F-HC	N/A
T-72G-HC-FGD01	N/A
T-19E-HC	N/A
T-19FZ-HC	N/A
GDM-07-HC~TSL01	LOCK IS NOT REPLACEABLE - FOAMED IN TO DOOR. LOCK IS LOCATED IN THE BOTTOM OF THE DOOR.
TS-72-HC	N/A
T-23F-2-MC	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOOR ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR.
T-35F-HC	N/A
T-23F-2-MC-BK	STARTED USING ON 1/6/2009. REPLACES/RETROFITS PREVIOUS (831305) LOCK ASSEMBLY. (PCN #4115) FOR TOP DOOR ONLY. BOTTOM DOOR HAS LOCK BAR ONLY THAT CONNECT/LOCK TOP DOOR TO BOTTOM DOOR.
T-49G-HC~FGD01	N/A
TS-35F-HC	N/A
T-35G-HC~FGD01	N/A
TS-49-HC	N/A
T-49FG-HC~FGD01	N/A
T-19-HC	N/A
T-23G-PT-HC-FGD01	N/A
T-19G-HC~FGD01	N/A

T-19F-HC	N/A
T-23PT-HC	N/A
T-49G~FGD01	N/A
T-23G-HC~FGD01	N/A
T-72FG-HC~FGD01	N/A
T-35G~FGD01	N/A
T-23-2-HC	N/A
T-23DT-HC	N/A
T-23DT-G-HC~FGD01	N/A
T-23FG-HC~FGD01	N/A
T-49G-4-HC~FGD01	N/A
TS-49G-4-HC~FGD01	N/A
T-49-2-G-2HC~FGD01	N/A
TS-49-2-G-2HC~FGD01	N/A
T-49DT-HC	LOCK IS NOT REPLACEABLE - FOAMED IN TO DOOR. LOCK IS LOCATED IN THE BOTTOM OF THE DOOR.
T-49DT-4-HC	LOCK IS NOT REPLACEABLE - FOAMED IN TO DOOR. LOCK IS LOCATED IN THE BOTTOM OF THE DOOR.