



Lavex Pro

Item #: 30BLP10TNMMFMBK Project: _____

Qty: _____ Date: _____ Approval: _____

Lavex Pro 34 fl. oz. (1,000 mL) Titanium Manual Foam Soap / Sanitizer Dispenser

Item #30BLP10TNMMFMBK



Technical Data

Length	9 1/8 Inches
Width	4 7/8 Inches
Height	4 1/2 Inches
Capacity	1000 mL 34 oz.
Color	Silver
Dispenser Style	Wall Mount
Dispenser Type	Push Button
Features	Locking Window

Features

- Holds 34 fl. oz. (1,000 mL) of foam soap or sanitizer (sold separately)
- Attractive, high-quality titanium finish
- Front viewing window and transparent sides help indicate when it's time to refill
- Easy to install with the included mounting hardware
- Includes a lock and key to prevent unauthorized access

Certifications



Recycled Content



Lavex Pro

Technical Data

Finish	Satin
Material	Plastic
Package Type	Bulk
Power Type	Manual
Refill Compatibility	Universal
Style	Foaming
Type	Dispensers Soap Dispensers

Notes & Details

Promote hygiene in your establishment with this Lavex manual soap dispenser. This high-quality dispenser features a sleek titanium finish to complement most restroom interiors and fixtures. It is coated in premium paint to maintain an attractive, high-end appearance, and it features a durable plastic construction made with recycled materials. This soap dispenser features a large 34 fl. oz. (1,000 mL) capacity to minimize the need for refills. It is manually operated with a simple push button.

This dispenser includes a front viewing window and transparent sides to easily keep track of the soap level and know when it's time to refill. It is easily refillable, and it is designed to be used with foam soap and sanitizer only (sold separately). This dispenser is easy to install with the included mounting hardware. Plus, it includes a lock and key to prevent unauthorized access. Great for high-traffic restrooms, this reliable dispenser is perfect for quick, convenient soap dispensing.

⚠ WARNING: This product can expose you to chemicals including lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. For more information, go to www.p65warnings.ca.gov.